

INSPECTION REPORT

Inspector's Name VOIGT, MILO		Inspector's Signature			Inspector's ID No. 92200	Report No. 68	Date yy mm dd 2024 05 21						
Railroad/Company Name & Address ALASKA RR CORP.				R/C R	Division SYSTEM	RR/Co. Representative (Receipt Acknowledged) Name Patrick Durand							
Wasilla AK				RR/Co. Code ARR	Subdivision SYSTEM	Title							
						Email sewtrain557@gmail.com							
						Signature _____							
From: City WASILLA	Codes 2790	Destination City & County			Codes	From Latitude							
State AK	02	City				From Longitude							
County MATANUSKA SUSITNA	C170	County				To Latitude							
Mile Post: From	To	Inspection Point ENGINE 557 WASILLA				To Longitude							
Activity Code:	230												
Units:	1												
Sub Units:	0												
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	ARR	557	STM	230	0036	A1				N	N	0	
Description - [** Comment to Railroad/Company **] No exception taken during observation of satisfactory hydrostatic test of steam locomotive boiler. MWAP 225psi, tested at 281psi, water temperature 90 degrees.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended				<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is:				<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?			